

**NELSON MANDELA METROPOLITAN MUNICIPALITY  
 INFRASTRUCTURE & ENGINEERING BUSINESS UNIT  
 SUPPORT SERVICES  
 SCIENTIFIC SERVICES  
 CERTIFICATE OF ANALYSIS**

Ndlambe Municipality P.O. Box 13 Port Alfred 6170 (Fax: 046 604 2751) Tel # : 046 604 2750

PARTICULARS OF SAMPLE: Untreated Tap Water Samples for Bacteriological Analysis.

SUBMITTED BY : S Tshayina

DATE RECEIVED : 2014-04-02

DATE OF REPORT : 2014-04-03

e-mail: vmfo@ndlambe.gov.za/

umtyobo@ndlambe.gov.za /

**ALL SAMPLES WERE ANALYSED ACCORDING TO APPROVED**

Sample #	23	24
<b>Sample Identification</b>	Bathurst reservoir- untreated	Nemato reservoir- untreated
TOTAL Coliforms per 100 ml	>2000	>2000
E.coli per 100 ml	<10	<10
<p>This report relates only to sample/s supplied to the SCIENTIFIC SERVICES DIVISION and does not relate to similar samples. This report may not be reproduced, except in full, without the written approval of the Chief Scientific Officer. Although SCIENTIFIC SERVICES will endeavour to perform analyses correctly, neither SCIENTIFIC SERVICES nor its members shall be liable for loss or damage attributed directly or indirectly to the inaccuracy of analyses or their interpretation. Results not queried within 10 working days of the issuing of the report will result in the disposal of the original samples, unless SCIENTIFIC SERVICES DIVISION are advised to the contrary.</p>		
<p>ASSISTANT DIRECTOR SCIENTIFIC SERVICES:            .....</p>		